




# AGA CERTIFIED PRODUCT

Certificate Holder: **EBRO ARMATUREN PACIFIC PTY LTD**  
ABN/ACN No. (if applicable): **82 090 475 951**  
Manufacturer: **Ebro Armaturen, GmbH, Germany**  
Agent (if applicable): **N/A**  
Type of Component: **Actuated Butterfly Valves**  
Model No. & Description: **EBRO ARMATUREN**  
(Refer [www.aga.asn.au](http://www.aga.asn.au) for more details)

JAS-ANZ



[www.jas-anz.org/register](http://www.jas-anz.org/register)

**Wafer Pattern Butterfly Valve**      **TYPE Z 011-A, PN-16**  
**Lug Type Butterfly Valve**      **TYPE Z 014-A, PN-16**

**Size range: DN40, DN50, DN65, DN80, DN100, DN125, DN150**  
**Actuator: EB-SYS Series**  
**Limit switch box: SBU-M203, SBU-M205 or SBU-M305**  
**Solenoid valve: Herion 96000 Series (Norgren 24V DC)**  
**Quick exhaust valve: HAFNER SENR 20 Series**

**Class: 1**  
**Maximum working pressure: 1600kPa**  
**Operating temperature range: -10°C to +70°C**

Relevant Standard(s): **AS4629-2005 (Inc. Amend. No.'s 1 & 2)**

This is to certify that the particular **COMPONENT** specifically described herein and supplied to The Australian Gas Association (hereafter called the AGA) by the Certificate Holder named above has been subject to "type-testing" and assessed by the AGA to comply with the requirements of the AGA's Product Certification Scheme for Type Tested Gas Products.

**This Certificate is issued on the express conditions that:**

- (i) The Certificate Holder undertakes to comply with the Rules Governing The AGA's Product Certification Scheme (hereafter called the Rules Governing);
- (ii) This Certificate remains the property of the AGA; and
- (iii) The AGA reserves the right to cancel this Certificate in accordance with the Rules Governing, and in such an event the Certificate Holder undertakes to surrender the Certificate to the AGA upon request.



**Client Manager**

**Certificate Authorised**

Certificate first issued: **14 July 2021**

Certificate No: **8962**

This copy valid from: **14 July 2021**

Refer specification issue: **01**